

Issue 627

PS

February
2005

THE PREVENTIVE MAINTENANCE MONTHLY

TB 43-PS-627

Approved for
Public Release;
Distribution is
Unlimited

PROTECTING
THE MOVER,
SHOOTER
AND
COMMUNICATOR



SEE
PAGES
27-34 &
46-48

FMTV PAINT PATTERNS

For the latest info on your FMTV's camouflage paint patterns, go to this website:

<http://peocscss.tacom.army.mil/pmMTV/index.html>

Once you're in the website, click on Logistics-Maintenance, and go to the first sub-bullet that says, Announcements. Scroll down on the right side of the screen to May 00 and click on FMTV Camouflage Paint Patterns. Select the vehicle you need info on.

A20 Heater Parts

The impeller and vent fan motor that make up the A20 personnel heater's vent fan motor assembly, NSN 6105-01-498-3867, can now be ordered separately. The NSN for the impeller is 4140-01-503-2369. But you can save a lot if all you need is the motor, NSN 6105-01-503-2368.

ROPE LOCK NSN

Order NSN 4030-01-477-0524 to get a rope lock that keeps a tent rope, loose gear, flight line or canvas cover snug. The rope lock doesn't need continual adjustments once it's secured or fastened. This NSN gets a package of 12 rope locks.

Windshield Wiper Actuator NSN

Use NSN 1680-01-483-2097 to order the windshield wiper actuator for your Chinook helicopter. The NSN shown for Item 7 in Fig 396 of TM 55-1520-240-23P-3 is wrong. Make a note until the TM is updated in the next change.

Finding NSNs for Unit Patches

Need to order colored or subdued unit uniform patches but don't have an NSN? Go to DLA's Clothing and Textiles website, Warfighters Clothing Support webpage at:

<http://ct.dscpl.dla.mil/Ascot/>

Search for SHOULDER SLEEVE INSIGNIA and scroll through the nearly 750 patches for the one belonging to your unit. Click on UNIVERSAL PRODUCT CODES to find the NSN.

Order M2 Recoil Buffer by Parts

Armorer's, your support can no longer order the M2 machine gun's recoil buffer as an assembly. Its SMR code has been changed to AFFFF, which means it must be ordered with the parts listed in Fig 6 of TM 9-1005-213-23&P. Make these changes on Page 0049 00-3/4:

- The SMR code for Item 6, barrel buffer body assembly, is now PAFZZ and its NSN is 1005-00-726-6835.
- The SMR code for Item 4, machine buffer accelerator, changes to PAFZZ.
- The correct NSN for Item 1, barrel buffer assembly, is NSN 1005-00-141-1235.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?

© U.S. GOVERNMENT PRINTING OFFICE: 2005 — 750-113/80027

For Sale by the Superintendent of Documents, U.S. Government Printing Office
Internet: bookstore.gpo.gov Phone: toll free (866) 512-1800; DC area (202) 512-1800
Fax: (202) 512-2250 Mail: Stop SSOP, Washington DC 20402-0001